## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Shannon Hotel
1 East Main Street
Christiana
New Castle County
Delaware

DE-190

Documentation: 4 sheets (1975, including site plan, plan, elevation,

section)

5 exterior photos (1982) 3 interior photos (1982)

8 data pages (1975)

1 set of field records (1 notebook, 10 photos)

Jack E. Boucher, Photographer July, 1982

DE-190-1 SOUTHWEST FRONT

DE-190-2 SOUTHWEST FRONT FROM SOUTH

DE-190-3 SOUTHWEST FRONT FROM WEST

DE-190-4 NORTHWEST SIDE AND SOUTHWEST FRONT

DE-190-5 NORTHWEST SIDE

DE-190-6 FIRST FLOOR, SOUTHWEST WALL, DETAIL OF LATH

DE-190-7 SECOND FLOOR, EAST ROOM, DETAIL OF FIREPLACE

DE-190-8 ATTIC, NEAR SOUTH CORNER, DETAIL OF RAFTER AND COLLAR BEAM